



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL.	MORGAN
Executive	Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:				
Company	Ian McClain Associate Engineer			
OGM	Karl Houskeeper Environmental Scientist III			

Inspection Report

Permit Number:	C0150015
Inspection Type:	PARTIAL
Inspection Date:	Monday, June 21, 2010
Start Date/Time:	6/21/2010 2:00:00 PM
End Date/Time:	6/21/2010 2:30:00 PM
Last Inspection:	Monday, June 14, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp 79 deg. F. InspectionID Report Number: 2402

Types of Operations

Reprocessing

Accepted by: jhelfric

6/24/2010

Permitee: CONSOLIDATION COAL CO

Operator:

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	442.50
Total Disturbed	248.50
Phase I	
Phase II	
Phase III	

Mineral Ownership

Other

✓ Federal ✓ Underground State Surface ☐ Loadout County Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Jaren Jorgensen Consol was present during the inspection.

The purpose of this partial inspection was to verify the abatement of Citation 10055. (See item 4a.)

Citation 10057 verification of abatement was done on 6/17/2010 by Priscilla Burton (DOGM). (see item 4c.)

Inspector's Signature:

Date

Tuesday, June 22, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Monday, June 21, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		V	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	a Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150015
Inspection Type: PARTIAL

Inspection Date: Monday, June 21, 2010

Page 3 of 3

4.a Hydrologic Balance: Diversions

The Division was notified in person (Karl Houskeeper) @ the SLC DOGM that Citation 10055 had been abated.

The culvert located at the base of the access road into the refuse pile has been cleaned and can now function as designed. Additional cleaning is scheduled to take place in the plain where the culvert outlet empties to prevent the culvert outlet from building up with sediment due to a gradual grade. Citation 10055 was terminated on 6/22/2010.

The abatement date was listed as 7/15/2010 on the Citation.

4.c Hydrologic Balance: Other Sediment Control Measures

Priscilla Burton (DOGM) conducted a field inspection on 6/17/2010 to verify that the abatement of Citation 10057 had taken place. The Division was notified (by phone, Karl Houskeeper) on 6/15/2010 that the silt fence had been replaced or repaired as required. The abatement date was listed as 7/15/2010 on the Citation. Citation 10057 was terminated on 6/22/2010.